Find Dop Certification for RADs

Quick Guide




Step 1- Find the product pindop number!


Find the product pindop number (Reference number Declaration of Performance) on the package of the product!

The pindop number is generated by an SAP label printer that prints it on the label of a product in the production.

The products from PLA and PBO have pindop number on their Label. PMA puts a sticker on the packaging or inside the packing with the DoP's




Step 2 – Insert in your web browser www.pindop.com






Step 3 – Select your language






Step 4 – Insert your DoP number of the product and then click Search button. DoP number is a unique identification code for each product-type.





Step 5 – See the results. To get the Dop in .pdf format you need to select PDF Download





Step 6 - The application will create the DoP certificate in .pdf format for save and print

